

REFURBISHED ANCILLARY EQUIPMENT.



Before Repair



Before Repair

Multiflow 150S Pump Module powered by C9 Caterpillar failed fan Assembly.

Unit was completely dismantled, fuel tank required repairs due to leaks and structural damage, Pump unit was only recently replaced and only required servicing, drive was rebuilt, Engine repairs were carried out and cooling system was overhauled as per client's direction. Structure was cleaned up and damage repaired as authorised, Unit was blasted, primed and final paint coated in two pack paint, Unit was performance tested, all shut downs were verified and repaired as needed before returning to site.

See finished item on following page.

REFURBISHED ANCILLARY EQUIPMENT.



Testing



Ready to Ship




Ready to Ship

REFURBISHED ANCILLARY EQUIPMENT.

Unit 2



Before Repair



Before Repair

Multiflow 200S Pump Module

This unit required a full rebuild and Engine upgrade due to age and condition, Unit was originally powered by 3204 Caterpillar and was Modernised using a Cummins 6B-5.9C power pack as requested by client. All electrics were upgraded to latest mine Specs and repaired as required, Wet end was rebuilt using all new components, Drive coupling was upgraded and aligned, Skid base was completely service including modifications to accept new Engine configuration. Unit was totally re-hosed and performance tested on completion of repairs, please see after Photo's on next page.

REFURBISHED ANCILLARY EQUIPMENT.



**After Rebuild
Multiflow 200S Pump Module.**

